

Downtown Reading Parking Study - Lighting Needs Assessment prepared by Police & DPW - March 2020

Assumption: poles exist, but most do not yet have lights on them.

Inner Core			
Road Segment	From:	To:	Assessment / Action
Sanborn St	Woburn St	Haven St	dark due to construction / re-evaluate once Postmark complete
Gould St	Haven St	10 Gould St	dark due to construction; may also be light out / re-evaluate once 24 Gould complete; contact RMLD
Lower Haven St			lights too high - needs additional lower lighting / address as part of future streetscape project
Atlantic Way			back entrance dark - needs additional lighting / ask owner of 30 Haven to install lighting on bldg to light access way
Brande Court Lot			decorative light poles in lot / ask owner of 30 Haven to install lighting on bldg to light lot
CVS Lot			dark near Woburn St entrance; needs additional lower lighting throughout lot / ask RMLD to add 2 LEDs to pole near 666 Main St; ask bldg owners to install lighting on bldgs
Train Depot area			very well lit

Outer Core			
Road Segment	From:	To:	Assessment / Action
Pleasant St	Middle St	John St	very dark / see if RMLD can add lights near 111 and 128 Pleasant
Intersection of Mt. Vernon St & Chute St			very dark / new LED light may not be working, DPW to contact RMLD
Senior Center Handicap Ramp			bldg shadows ramp / install LEDs on back of bldg to light ramp & lot
Harnden Lot			decorative light poles near lot; bldg lighting turned off when Walgreens closed / staff working with owner to activate space

Other	
Intersection of Washington St & Prescott St	ask RMLD to install new LED near 61/63 Washington St.